

The power output listed on page 12 of report 95059-8, the last column was incorrectly titled. The power reported is conducted output power.