




Figure 828: Spurious Emissions at Antenna Terminal 16QAM 20MHz B.W.; 1940.0MHz, 30kHz




Figure 829: Spurious Emissions at Antenna Terminal 16QAM 20MHz B.W.; 1962.5MHz, 30kHz




Figure 830: Spurious Emissions at Antenna Terminal 16QAM 20MHz B.W.; 1962.5MHz, 30kHz




Figure 831: Spurious Emissions at Antenna Terminal 16QAM 20MHz B.W.; 1940.0MHz, 15kHz




Figure 832: Spurious Emissions at Antenna Terminal 16QAM 20MHz B.W.; 1962.5MHz, 15kHz




Figure 833: Spurious Emissions at Antenna Terminal 16QAM 20MHz B.W.; 1985.0MHz, 60kHz




Figure 834: Spurious Emissions at Antenna Terminal 16QAM 25MHz B.W.; 1942.5MHz, 15kHz




Figure 835: Spurious Emissions at Antenna Terminal 16QAM 25MHz B.W.; 1962.5MHz, 15kHz




Figure 836: Spurious Emissions at Antenna Terminal 16QAM 25MHz B.W.; 1982.5MHz, 15kHz




Figure 837: Spurious Emissions at Antenna Terminal 16QAM 25MHz B.W.; 1942.5MHz, 30kHz




Figure 838: Spurious Emissions at Antenna Terminal 16QAM 25MHz B.W.; 1962.5MHz, 30kHz




Figure 839: Spurious Emissions at Antenna Terminal 16QAM 25MHz B.W.; 1982.5MHz, 30kHz




Figure 840: Spurious Emissions at Antenna Terminal 16QAM 25MHz B.W.; 1942.5MHz, 60kHz




Figure 841: Spurious Emissions at Antenna Terminal 16QAM 25MHz B.W.; 1962.5MHz, 60kHz




Figure 842: Spurious Emissions at Antenna Terminal 16QAM 25MHz B.W.; 1982.5MHz, 60kHz




Figure 843: Spurious Emissions at Antenna Terminal 16QAM 40MHz B.W.; 1950.0MHz, 15kHz




Figure 844: Spurious Emissions at Antenna Terminal 16QAM 40MHz B.W.; 1962.5MHz, 15kHz




Figure 845: Spurious Emissions at Antenna Terminal 16QAM 40MHz B.W.; 1975.0MHz, 15kHz




Figure 846: Spurious Emissions at Antenna Terminal 16QAM 40MHz B.W.; 1950.0MHz, 30kHz




Figure 847: Spurious Emissions at Antenna Terminal 16QAM 40MHz B.W.; 1962.5MHz, 30kHz




Figure 848: Spurious Emissions at Antenna Terminal 16QAM 40MHz B.W.; 1975.0MHz, 30kHz




Figure 849: Spurious Emissions at Antenna Terminal 16QAM 40MHz B.W.; 1950.0MHz, 60kHz




Figure 850: Spurious Emissions at Antenna Terminal 16QAM 40MHz B.W.; 1962.5MHz, 60kHz




Figure 851: Spurious Emissions at Antenna Terminal 16QAM 40MHz B.W.; 1975.0MHz, 60kHz




Figure 852: Spurious Emissions at Antenna Terminal 16QAM 50MHz B.W.; 1955.0MHz, 15kHz




Figure 853: Spurious Emissions at Antenna Terminal 16QAM 50MHz B.W.; 1962.5MHz, 15kHz




Figure 854: Spurious Emissions at Antenna Terminal 16QAM 50MHz B.W.; 1970.0MHz, 15kHz




Figure 855: Spurious Emissions at Antenna Terminal 16QAM 50MHz B.W.; 1955.0MHz, 30kHz




Figure 856: Spurious Emissions at Antenna Terminal 16QAM 50MHz B.W.; 1962.5MHz, 30kHz




Figure 857: Spurious Emissions at Antenna Terminal 16QAM 50MHz B.W.; 1970.0MHz, 30kHz




Figure 858: Spurious Emissions at Antenna Terminal 16QAM 50MHz B.W.; 1955.0MHz, 60kHz




Figure 859: Spurious Emissions at Antenna Terminal 16QAM 50MHz B.W.; 1962.5MHz, 60kHz




Figure 860: Spurious Emissions at Antenna Terminal 16QAM 50MHz B.W.; 1970.0MHz, 60kHz




Figure 861: Spurious Emissions at Antenna Terminal 16QAM 60MHz B.W.; 1960.0MHz, 30kHz




Figure 862: Spurious Emissions at Antenna Terminal 16QAM 60MHz B.W.; 1962.5MHz, 30kHz




Figure 863: Spurious Emissions at Antenna Terminal 16QAM 60MHz B.W.; 1965.0MHz, 30kHz




Figure 864: Spurious Emissions at Antenna Terminal 16QAM 60MHz B.W.; 1962.5MHz, 60kHz




Figure 865: Spurious Emissions at Antenna Terminal 16QAM 60MHz B.W.; 1965.0MHz, 30kHz




Figure 866: Spurious Emissions at Antenna Terminal 16QAM 60MHz B.W.; 1965.0MHz, 60kHz




Figure 867: Spurious Emissions at Antenna Terminal 64QAM 5MHz B.W.; 1932.5MHz, 15kHz




Figure 868: Spurious Emissions at Antenna Terminal 64QAM 5MHz B.W.; 1962.5MHz, 15kHz




Figure 869: Spurious Emissions at Antenna Terminal 64QAM 5MHz B.W.; 1992.5MHz, 15kHz




Figure 870: Spurious Emissions at Antenna Terminal 64QAM 5MHz B.W.; 1932.5MHz, 30kHz




Figure 871: Spurious Emissions at Antenna Terminal 64QAM 5MHz B.W.; 1962.5MHz, 30kHz




Figure 872: Spurious Emissions at Antenna Terminal 64QAM 5MHz B.W.; 1992.5MHz, 30kHz




Figure 873: Spurious Emissions at Antenna Terminal 64QAM 10MHz B.W.; 1935.00MHz, 15kHz




Figure 874: Spurious Emissions at Antenna Terminal 64QAM 10MHz B.W.; 1962.50MHz, 15kHz




Figure 875: Spurious Emissions at Antenna Terminal 64QAM 10MHz B.W.; 1990.00MHz, 15kHz




Figure 876: Spurious Emissions at Antenna Terminal 64QAM 10MHz B.W.; 1935.00MHz, 30kHz




Figure 877: Spurious Emissions at Antenna Terminal 64QAM 10MHz B.W.; 1962.5MHz, 30kHz




Figure 878: Spurious Emissions at Antenna Terminal 64QAM 10MHz B.W.; 1990.00MHz, 30kHz




Figure 879: Spurious Emissions at Antenna Terminal 64QAM 10MHz B.W.; 1935.0MHz, 60kHz




Figure 880: Spurious Emissions at Antenna Terminal 64QAM 10MHz B.W.; 1962.5MHz, 60kHz




Figure 881: Spurious Emissions at Antenna Terminal 64QAM 10MHz B.W.; 1990.0MHz, 60kHz




Figure 882: Spurious Emissions at Antenna Terminal 64QAM 15MHz B.W.; 1937.5MHz, 15kHz




Figure 883: Spurious Emissions at Antenna Terminal 64QAM 15MHz B.W.; 1962.5MHz, 15kHz




Figure 884: Spurious Emissions at Antenna Terminal 64QAM 15MHz B.W.; 1962.5MHz, 15kHz




Figure 885: Spurious Emissions at Antenna Terminal 64QAM 15MHz B.W.; 1937.5MHz, 30kHz




Figure 886: Spurious Emissions at Antenna Terminal 64QAM 15MHz B.W.; 1962.5MHz, 30kHz




Figure 887: Spurious Emissions at Antenna Terminal 64QAM 15MHz B.W.; 1987.5MHz, 30kHz




Figure 888: Spurious Emissions at Antenna Terminal 64QAM 15MHz B.W.; 1937.5MHz, 60kHz




Figure 889: Spurious Emissions at Antenna Terminal 64QAM 15MHz B.W.; 1962.5MHz, 60kHz




Figure 890: Spurious Emissions at Antenna Terminal 64QAM 15MHz B.W.; 1987.5MHz, 60kHz




Figure 891: Spurious Emissions at Antenna Terminal 64QAM 20MHz B.W.; 1940.0MHz, 15kHz




Figure 892: Spurious Emissions at Antenna Terminal 64QAM 20MHz B.W.; 1962.5MHz, 15kHz




Figure 893: Spurious Emissions at Antenna Terminal 64QAM 20MHz B.W.; 1985.0MHz, 15kHz




Figure 894: Spurious Emissions at Antenna Terminal 64QAM 20MHz B.W.; 1940.0MHz, 30kHz




Figure 895: Spurious Emissions at Antenna Terminal 64QAM 20MHz B.W.; 1962.5MHz, 30kHz




Figure 896: Spurious Emissions at Antenna Terminal 64QAM 20MHz B.W.; 1985.0MHz, 30kHz




Figure 897: Spurious Emissions at Antenna Terminal 64QAM 20MHz B.W.; 1940.0MHz, 60kHz




Figure 898: Spurious Emissions at Antenna Terminal 64QAM 20MHz B.W.; 1962.5MHz, 60kHz




Figure 899: Spurious Emissions at Antenna Terminal 64QAM 20MHz B.W.; 1985.0MHz, 60kHz




Figure 900: Spurious Emissions at Antenna Terminal 64QAM 25MHz B.W.; 1942.5MHz, 15kHz




Figure 901: Spurious Emissions at Antenna Terminal 64QAM 25MHz B.W.; 1962.5MHz, 15kHz




Figure 902: Spurious Emissions at Antenna Terminal 64QAM 25MHz B.W.; 1982.5MHz, 15kHz




Figure 903: Spurious Emissions at Antenna Terminal 64QAM 25MHz B.W.; 1942.5MHz, 30kHz




Figure 904: Spurious Emissions at Antenna Terminal 64QAM 25MHz B.W.; 1962.5MHz, 30kHz




Figure 905: Spurious Emissions at Antenna Terminal 64QAM 25MHz B.W.; 1982.5MHz, 30kHz




Figure 906: Spurious Emissions at Antenna Terminal 64QAM 25MHz B.W.; 1942.5MHz, 60kHz




Figure 907: Spurious Emissions at Antenna Terminal 64QAM 25MHz B.W.; 1962.5MHz, 60kHz




Figure 908: Spurious Emissions at Antenna Terminal 64QAM 25MHz B.W.; 1982.5MHz, 60kHz




Figure 909: Spurious Emissions at Antenna Terminal 64QAM 40MHz B.W.; 1950.0MHz, 15kHz




Figure 910: Spurious Emissions at Antenna Terminal 64QAM 40MHz B.W.; 1962.5MHz, 15kHz




Figure 911: Spurious Emissions at Antenna Terminal 64QAM 40MHz B.W.; 1975.0MHz, 15kHz




Figure 912: Spurious Emissions at Antenna Terminal 64QAM 40MHz B.W.; 1950.0MHz, 30kHz




Figure 913: Spurious Emissions at Antenna Terminal 64QAM 40MHz B.W.; 1962.5MHz, 30kHz




Figure 914: Spurious Emissions at Antenna Terminal 64QAM 40MHz B.W.; 1975.0MHz, 30kHz