

Correspondence by Project

Project Number:

982591462

Correspondence Number	Memo
OJMOTX400HHKF-1	1) The block diagram submitted is not sufficient. As per section 2.1033(b)(5) of the FCC rules, the block diagram must show "the frequency of all oscillators used in the device. The signal path and frequency shall be indicated at each block. The tuning range(s) and intermediate frequency(ies) shall be indicated at each block." Response: The Block Diagram has been revised and uploaded. 2) The modification letter provided shows a different modification than the one shown in the report. Please provide a new modification letter. Response: The modification letter has been revised and uploaded. 3) Please provide a diagram showing the location of the FCC ID label. Response: The FCC ID Label location has been uploaded.