

A

Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046

Dear FCC:

When form 731 was filled out electronically, a mistake was made in the product code part of the FCC ID number for the Scitronics CS1000 System consisting of the DSP1000 Receiver (WI10-02) and the BT10-02 Transmitter. The correct FCC ID Number should be OPTDSP1000QT900. Please correct accordingly.

Thank you,

Kristi Iwen
EMC Technical Secretary
Intertek Testing Services
7435 4th Street North
Oakdale, MN 55128