

Test report 99365730

Corrigendum



Contents

CORRIGENDUM.....	3
1 SCOPE	3
2 SUBJECT	3
3 ACTIONS.....	3
CONCLUSIONS.....	4

Corrigendum

1 Scope

Telefication Test Report 99365730, all sections.

2 Subject

FCC ID.


3 Actions

Replace all occurrences of “**FCC ID: QQSECIST4120**” by “**FCC ID: OQSRTU4120A**”.


Conclusions

All conclusions, test and measurement results and any other relevant information as reported in Telefication Test Report 99365730, remain valid after effectuation of the above mentioned corrective measure.

The above mentioned corrective measure has been verified by the following signatory:

name : ing. P.A. Suringa
function : Senior Engineer Radio/EMC
signature : 

The above conclusions have been verified by the following signatory:

date : 23 January 2003
name : J.P. van de Poll
function : Co-ordinator Test Group
signature : 

Test report 99365730

Corrigendum



Contents

CORRIGENDUM.....	3
1 SCOPE	3
2 SUBJECT	3
3 ACTIONS.....	3
CONCLUSIONS.....	4

Corrigendum

1 Scope

Telefication Test Report 99365730, all sections.

2 Subject

FCC ID.


3 Actions

Replace all occurrences of “**FCC ID: QQSECIST4120**” by “**FCC ID: OQSRTU4120A**”.

Conclusions

All conclusions, test and measurement results and any other relevant information as reported in Telefication Test Report 99365730, remain valid after effectuation of the above mentioned corrective measure.

The above mentioned corrective measure has been verified by the following signatory:

name : ing. P.A. Suringa
function : Senior Engineer Radio/EMC
signature : 

The above conclusions have been verified by the following signatory:

date : 23 January 2003
name : J.P. van de Poll
function : Co-ordinator Test Group
signature : 