



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

April 29, 2005

RE: Globlink Technology Inc.

FCC ID: OR7GTM9300-9301

I have a few comments on this Application. Depending on your responses, kindly understand there may be additional comments.

- 1.) The Manual is missing the required compliance information. This includes the two-part statement of 15.19(a)(3), and the information to the user of 15.21. Please review.

A: Page 7 of the manual has gone. Revised one has been uploaded.

- 2.) Kindly review the Operational Description. What is an "angel limit"?

A: There is no angel limit for this antenna. We have informed the customer and uploaded the revised one.

- 3.) The Test Report does not indicate a loop antenna was used for measuring fundamental emissions at 27MHz. Please re-measure.

A: Thanks for your reminding, we have changed the test report format in case the same mistake happened again.

- 4.) Please provide evidence of compliance at the band edges at 26.96 and 27.28MHz as required by 15.27(b) and 15.209(b).

A: Please reference the plot on page 7 of revised test report.

William H. Graff
President and Director of Engineering

[mailto: whgraff@AmericanTCB.com](mailto:whgraff@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.