

MFA M. Flom Associates, Inc.
Global Compliance Center

3356 N. San Marcos Pl., Suite 107
Chandler, Arizona 85225-7176
(480) 926-3100, FAX: -3598
general@mflom.com
www.mflom.com

July 26th, 2000

FEDERAL COMMUNICATIONS COMMISSION
VIA Electronic Filing


Applicant: LightSpeed Technologies Inc.
Equipment: FCC ID: ORVLES-311TX EA97792
Correspondence 14946

1. Attached please find Addendum to Test Report (2 pages) for Audio Frequency Response.
2. Letter "Reply to FCC Correspondence 14883" now being resent. It addresses Rule 95.1019 and the antenna used.
3. The following statement will appear in User Manual, per Section 95.1017(a) and on the Transmitter as well.

"This device may not interfere with TV reception or Federal Government Radar, and must accept any interference received, including interference that may cause undesired operation'.

We trust this is the information required and that the Grant will be issued A.S.A.P.

Sincerely yours,


MORTON FLOM, P. Eng.

mf;mgf
encs.

cc: Applicant: FAX: 1 503 684 3197

cc: A2LA Corrective Action File