



INTERTEK TESTING SERVICE

Report No.: 14061336HKG-001

Equipment Photographs

Model : 80078TX

(Internal)



FCC ID: OTA80078TX
IC: 7783A-80078TX



INTERTEK TESTING SERVICE

Report No.: 14061336HKG-001

Equipment Photographs

Model : 80078TX

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14061336HKG-001

Equipment Photographs

Model : 80078TX

(Internal)



FCC ID: OTA80078TX
IC: 7783A-80078TX



INTERTEK TESTING SERVICE

Report No.: 14061336HKG-001

Equipment Photographs

Model : 80078TX

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14061336HKG-001

Equipment Photographs

Model : 80078TX

(Internal)



FCC ID: OTA80078TX
IC: 7783A-80078TX



INTERTEK TESTING SERVICE

Report No.: 14061336HKG-001

Equipment Photographs

Model : 80078TX

(Internal)



FCC ID: OTA80078TX
IC: 7783A-80078TX


INTERTEK TESTING SERVICE

Report No.: 14061336HKG-001

Equipment Photographs

Model : 80078TX

(Internal)



FCC ID: OTA80078TX
IC: 7783A-80078TX