JAKKS PACIFIC, (HK) LTD.

Room 1008 Peninsula Centre, 67 Mody Road,
Tsimshatsui East, Kowloon, Hong Kong
Tel 22697914 Fax 23110905

December 5, 2000

To ITS Intertek Testing Services
Attn Vivian Lui

Pls. note the FCC ID that we used to apply for the item C55005 of my company is originally designed as OTA C55005. The sample was submitted to your office by the mid of November. However, during the application process, we mistyped it as OTA55005. I was wondered if you could help to change the FCC ID from OTA55005 to OTAC55005.

For further enquiry, pls. feel free to contact me at the phone no. 22697914

Sincerely,
Henry Lo