

Request for Class II Permissive Change

FCC ID: OU9AW8001-LS

Data: December 02, 2014

TO: Federal Communication Commission

Please be notified that we, the undersigned, Guangdong Transtek Medical Electronics Co., Ltd declare that the reasons for this Class II permissive change are as below:

1. Update Host.

Please refer to below form for detailed information:

Item	Key Components Deviation		Remark
	LS203-B	GBF-1251-B, GBF-1251-B1, GBF-1251-B1 Plus, BF-1255-B, BF-1255-B1, BF-1255-B1 Plus	
Host	Wireless control Body Fat Analyzer	Glass Body Fat Analyzer	Model difference being the appearance, model name, shell and software.

Thank you.

Sincerely,


Zhongshan Transtek Electronics Co., Ltd

Tel: +86-760-88282982-230

Fax: +86-760-85339231

Email: kevintan@transtek.cn