

APPENDIX 3: Photographs of test setup

Radiated Emission LF ANT (Front)



Photo 1



Photo 2

Radiated Emission
LF ANT (Rear)




Photo 1




Photo 2

Worst Case Position

BCM
Below 30MHz
X-axis
Above 30MHz
Horizontal:Z-axis / Vertical:Z-axis
X-axis



Y-axis



Z-axis



LF ANT (Front)
Below 30MHz
X-axis
Above 30MHz
Horizontal:X-axis / Vertical:X-axis
X-axis



Y-axis



Z-axis



UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

LF ANT (Rear)

Below 30MHz

X-axis

Above 30MHz

Horizontal:X-axis / Vertical:X-axis

X-axis



Y-axis



Z-axis



End of Report

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124