

APPENDIX 3: Photographs of test setup

Radiated Emission




Photo 1





Photo 2


Worst Case Position

Immobilizer


Below 30MHz: X
Above 30MHz: Horizontal Z, Vertical Z
X-axis



Y-axis



Z-axis



ECU

Below 30MHz: X
Above 30MHz: Horizontal X, Vertical X
X-axis



Y-axis



Z-axis



UL Japan, Inc.


Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Worst case position



Mechanical Key (Not Inserted) Worst



Mechanical Key (Inserted)

End of Report