

> > -----

> > Matco Inc.

> >

> > FM2400 Revised: December 23,1999

> > Bill of materials December 23, 1999 Revision:

> > Bill of materials December 23, 1999

> >

> > Item	Qty	Reference	Part name	Sign
> > 001	4	CJ4, CJ5, CJ6, CJ32	CC150-00	15P
> > 002	1	R1	RC821-00	820R
> > 003	10	C8,C9,C10,C11,C12,C13	CC102-00	1n
> >		C14,C15,C16,C17		
> > 004	2	C23,C7	CB105-00	1uF 0805
> > 005	1	R13	RC124-00	120K
> > 006	2	R17,R16	RC473-00	47K
> > 007	2	R11,R10	RC100-00	10R
> > 008	1	C30	CC101-00	100P
> > 009	1	Q10	TC007-00 2SC3356	R24/R25
> > 010	3	R4,R2,R3	RC151-00	150R
> > 011	2	R27,R26	RC562-00	5.6K
> > 012	1	D1 DV006-00 HVU316-TRU		
> > 013	8	C27,C2,C22,C25,C26,C28	CC104-00	100n
> > 013	0	C1,C41		
> > 014	2	R12,R18	RC393-00	39K
> > 015	3	R33,R28,R36	RC102-00	1K
> > 016	1	R29	RC472-00	4.7K
> > 017	1	R9	RC220-00	22R
> > 018	2	R5,R6	RC101-00	100R
> > 019	1	R8	RC390-00	39R
> > 020	1	R7	RC910-00	91R
> > 021	1	R32	RC222-00	2.2K
> > 022	2	Q1,Q2	TC011-00 BFP182R	
> > 023	7	R111,R19,R20,R21,R22,R23	RC223-00	22K R100
> > 024	2	R34,R35	RC104-00	100K
> > 025	1	C31	CC200-00	20P
> > 026	3	C18,C19,C20	CC103-00	10n
> > 027	1	C4	CB220-TH	22P
> > 028	2	C6,C5	CB390-UJ	39P
> > 029	1	C3	CB180-TH	18P TH
> > 030	2	R31,R30	RC272-00	2.7K
> > 031	1	R14	RC913-00	91K
> > 032	1	R25	RC153-00	15K
> > 033	1	R15	RC823-00	82K
> > 034	3	CJ2,CJ1,CJ3	CJ202-12	2000P
> > 035	2	L2,L3	LV501-22 AL0.4*1.4*1.5	
> > 036	1	R21	RC000-00	OR
> > 037	1	SMA CONNECTOR 5M007-00	SMA CONNECTOR	
> > 038	1	PCB 3D056-11 FM VIDEO/AUDIO TXPCB		
> > 039	1	FRAME 1A002-11 70M FRAME (F CONNECTOR)		
> > 040	1	TOP COVER 1T002-14 WCOVER		
> > 041	1	BOTTOM COVER 1B002-12 70M BOTTOM COVER		
> > 042	6	Q4,Q3,Q5,Q6,Q7,Q8	TC005-00 TR 2SC2412KT146R-K	
> > 043	1	Q9	TC013-00 2SC4081R T106-K	
> > 044	1	IC1	IM011-00 SP5055GS	
> > 045	4	C37,C34,C35,C38	CCR50-00	0.5P

> > 046	1	X1	FX004-00 H4.0000	D4
> > 047	2	IF1,IF2	LK013-00	
> > 048	2	R50,R51	RA102-08	1K
> > 049	1	VR1	RV102-05 1KR 5mm F637V	
> > 051	1	C33	CC100-00	10P
> > 052	2	C39,C36	CC1R5-00	1.5P
> > 053	1	C29	CC560-00	56P
> >	-----			