



360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>

## **APPENDIX I: INTERNAL EUT PICTURES**


### **PHOTOGRAPH 5: INSIDE COVER**





360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>


**PHOTOGRAPH 6: MAIN PCB IN CHASSIS**





360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>


**PHOTOGRAPH 7: FRONT SHOWING LCD PCB IN CHASSIS**





360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>


## **PHOTOGRAPH 8: INSIDE CHASSIS**





360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>


**PHOTOGRAPH 9: LCD PCB FRONT SIDE**





360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>


**PHOTOGRAPH 10: LCD PCB BACK**





360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>


**PHOTOGRAPH 11: MAIN PCB TOP WITH SHIELDS**





360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>


**PHOTOGRAPH 12: MAIN PCB TOP WITH SHIELDS REMOVED**





360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>

**PHOTOGRAPH 13: MAIN PCB BOTTOM WITH SHIELDS**





360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>

**PHOTOGRAPH 14: MAIN PCB BOTTOM SHIELDS REMOVED**

