


Internal photos

Model: APS811


Test Report No.:	50345705 001	Page 1 of 12
------------------	---------------------	--------------



Internal photos

Model: APS811


Test Report No.:	50345705 001	Page 2 of 12
------------------	---------------------	--------------



Internal photos

Model: APS811


Test Report No.:	50345705 001	Page 3 of 12
------------------	---------------------	--------------



Internal photos

Model: APS811


Test Report No.:	50345705 001	Page 4 of 12
------------------	---------------------	--------------



Internal photos

Model: APS811


Test Report No.:	50345705 001	Page 5 of 12
------------------	---------------------	--------------



Internal photos

Model: APS811


Test Report No.:	50345705 001	Page 6 of 12
------------------	---------------------	--------------



Internal photos

Model: APS811


Test Report No.:	50345705 001	Page 7 of 12
------------------	---------------------	--------------



Internal photos

Model: APS811


Test Report No.:	50345705 001	Page 8 of 12
------------------	---------------------	--------------



Internal photos

Model: APS811


Test Report No.:	50345705 001	Page 9 of 12
------------------	---------------------	--------------



Internal photos

Model: APS811


Test Report No.:	50345705 001	Page 10 of 12
------------------	---------------------	---------------



Internal photos

Model: APS811

Test Report No.:	50345705 001	Page 11 of 12
------------------	---------------------	---------------



Internal photos

Model: APS811

Test Report No.:	50345705 001	Page 12 of 12
------------------	--------------	---------------

