


Report No.: 0300702
Model No.: N/A

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement

hp MKR 12.500 msec
REF 97.0 dBμV AT 10 dB .05 dB

PEAK
LOG
10
dBμ



VA SB
SC FC
CORR

Tested By: *[Signature]*
(Anthony Pan)

Date: 22-1-03

Checked By: *[Signature]*
(Anthony Pan)

Date: 23/1/03

Test Result: Pass / Fail / NA

CENTER 49.850 MHz SPAN 0 Hz
#RES BW 3.0 MHz #VBW 3 MHz #SWP 50.0 msec

Report No.: 0300702
Model No.: N/A

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement

hp

MARK 12.550 msec

REF 97.0 dBm

AT 10 dB


.00 dB

PEAK

LOG

10

dB



VA SB

SC FC

CORR

Tested By:

(Signature)
(Gary L. J.)

Date:

22-1-03

Checked By:

(Signature)
(Anthony Chan)

Date:

23/1/03

Test Result : Pass / Fail / NA

CENTER 49.850 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SNP 20.0 msec

INTERTEK TESTING SERVICES

Report No.: 0300702
Model No.: MA

Pursuant to FCC Part 15 Section 15. 255 Emissions Requirement

hp

MKHZ 750.00 μ SEC

REF 97.0 dB μ V

AT 10 dB


-1.06 dB

PEAK

LOG

10

dB



VA 50

SC FC

CORR

Tested By:

(Signature)
Chengli

Date: 22-1-03

Checked By:

(Signature)
Anthony Chan

Date: 23/1/03

Test Result : Pass / Fail / NA

CENTER 49.860 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SNP 20.0 msec

INTERTEK TESTING SERVICES

Report No.: 0300702
Model No.: N/A

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement

MKR 250.00 μ sec

REF 97.0 dB μ V

AT 10 dB


-.42 dB

PEAK

LOG

10

dB



VA SB

SC MC

CORR

Tested By:

[Signature]
(Craig)

Date: 22-1-03

Checked By:

[Signature]
(Anthony Chen)

Date: 23/1/03

Test Result: Pass / Fail / NA

CENTER 49.660 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 20.0 msec