



8.5.45 12.5 kHz, FM, UL Mask C, AGC, 788 MHz




10:39:55 05.03.2026

8.5.46 12.5 kHz, FM, UL Mask C, AGC+3, 788 MHz




10:41:57 05.03.2026

8.5.47 25 kHz FM, UL Mask C, AGC, 788 MHz




10:45:15 05.03.2026

8.5.48 25 kHz FM, UL Mask C, AGC+3, 788 MHz




10:46:25 05.03.2026

8.5.49 C4FM, UL Mask C, AGC, 788 MHz




14:00:35 05.03.2026

8.5.50 C4FM, UL Mask C, AGC+3, 788 MHz




14:02:21 05.03.2026

8.5.51 H-CPM, UL Mask C, AGC, 788 MHz




14:03:53 05.03.2026

8.5.52 H-CPM, UL Mask C, AGC+3, 788 MHz




14:12:00 05.03.2026

8.5.53 H-DQPSK, UL Mask C, AGC, 788 MHz




14:13:36 05.03.2026

8.5.54 H-DQPSK, UL Mask C, AGC+3, 788 MHz




14:14:32 05.03.2026

8.555 6.25 kHz, FM, UL Mask C, AGC, 791 MHz




11:03:30 05.03.2026

8.5.56 6.25 kHz, FM, UL Mask C, AGC+3, 791 MHz




11:06:32 05.03.2026

8.5.57 12.5 kHz, FM, UL Mask C, AGC, 791 MHz



11:07:43 05.03.2026

8.5.58 12.5 kHz, FM, UL Mask C, AGC+3, 791 MHz



11:08:47 05.03.2026