



8.5.59 25 kHz FM, UL Mask C, AGC, 791 MHz




11:09:50 05.03.2026

8.5.60 25 kHz FM, UL Mask C, AGC+3, 791 MHz




11:11:36 05.03.2026

8.5.61 C4FM, UL Mask C, AGC, 791 MHz




11:06:33 06.03.2026

8.5.62 C4FM, UL Mask C, AGC+3, 791 MHz




11:08:29 06.03.2026

8.5.63 H-CPM, UL Mask C, AGC, 791 MHz




11:09:59 06.03.2026

8.5.64 H-CPM, UL Mask C, AGC+3, 791 MHz




11:11:08 06.03.2026

8.5.65 H-DQPSK, UL Mask C, AGC, 791 MHz




11:12:20 06.03.2026

8.5.66 H-DQPSK, UL Mask C, AGC+3, 791 MHz




11:13:18 06.03.2026

8.5.67 6.25 kHz, FM, UL Mask C, AGC, 794 MHz




11:13:50 05.03.2026

8.5.68 6.25 kHz, FM, UL Mask C, AGC+3, 794 MHz




11:14:49 05.03.2026

8.5.69 12.5 kHz, FM, UL Mask C, AGC, 794 MHz




11:15:56 05.03.2026

8.5.70 12.5 kHz, FM, UL Mask C, AGC+3, 794 MHz




11:16:51 05.03.2026

8.5.71 25 kHz FM, UL Mask C, AGC, 794 MHz




11:18:09 05.03.2026

8.5.72 25 kHz FM, UL Mask C, AGC+3, 794 MHz



11:19:18 05.03.2026

8.5.73 C4FM, UL Mask C, AGC, 794 MHz



11:25:34 06.03.2026