



8.5.66 H-DQPSK, UL Mask C, AGC+3, 788 MHz




14:33:34 05.05.2026

8.5.67 6.25 kHz, FM, UL Mask C, AGC, 793 MHz




08:03:59 07.05.2026

8.5.68 6.25 kHz, FM, UL Mask C, AGC+3, 793 MHz




08:04:35 07.05.2026

8.5.69 12.5 kHz, FM, UL Mask C, AGC, 793 MHz




08:07:04 07.05.2026

8.5.70 12.5 kHz, FM, UL Mask C, AGC+3, 793 MHz




08:08:09 07.05.2026

8.5.71 25 kHz FM, UL Mask C, AGC, 793 MHz




08:09:50 07.05.2026

8.5.72 25 kHz FM, UL Mask C, AGC+3, 793 MHz




08:09:15 07.05.2026

8.5.73 C4FM, UL Mask C, AGC, 793 MHz




14:54:46 05.05.2026

8.5.74 C4FM, UL Mask C, AGC+3, 793 MHz



14:56:58 05.05.2026

8.5.75 H-CPM, UL Mask C, AGC, 793 MHz




14:59:52 05.05.2026

8.5.76 H-CPM, UL Mask C, AGC+3, 793 MHz




15:01:16 05.05.2026

8.5.77 H-DQPSK, UL Mask C, AGC, 793 MHz




15:04:20 05.05.2026

8.5.78 H-DQPSK, UL Mask C, AGC+3, 793 MHz




15:05:14 05.05.2026

8.5.79 6.25 kHz, FM, UL Mask C, AGC, 797 MHz




07:53:22 07.05.2026

8.5.80 6.25 kHz, FM, UL Mask C, AGC+3, 797 MHz




07:54:10 07.05.2026

8.5.81 12.5 kHz, FM, UL Mask C, AGC, 797 MHz




07:54:54 07.05.2026

8.5.82 12.5 kHz, FM, UL Mask C, AGC+3, 797 MHz




07:55:23 07.05.2026

8.5.83 25 kHz FM, UL Mask C, AGC, 797 MHz



07:57:50 07.05.2026

8.5.84 25 kHz FM, UL Mask C, AGC+3, 797 MHz




07:58:31 07.05.2026

8.5.85 C4FM, UL Mask C, AGC, 797 MHz




14:40:56 05.05.2026

8.5.86 C4FM, UL Mask C, AGC+3, 797 MHz



14:44:28 05.05.2026

8.5.87 H-CPM, UL Mask C, AGC, 797 MHz



16:14:54 20.05.2026

8.5.88 H-CPM, UL Mask C, AGC+3, 797 MHz




16:17:05 20.05.2026

8.5.89 H-DQPSK, UL Mask C, AGC, 797 MHz




14:48:20 05.05.2026

8.5.90 H-DQPSK, UL Mask C, AGC+3, 797 MHz




14:49:38 05.05.2026

8.5.91 6.25 kHz, FM, UL Mask C, AGC, 804 MHz




08:12:56 07.05.2026

8.5.92 6.25 kHz, FM, UL Mask C, AGC+3, 804 MHz




08:14:03 07.05.2026

8.5.93 12.5 kHz, FM, UL Mask C, AGC, 804 MHz




08:14:46 07.05.2026

8.5.94 12.5 kHz, FM, UL Mask C, AGC+3, 804 MHz




08:15:22 07.05.2026

8.5.95 25 kHz FM, UL Mask C, AGC, 804 MHz




08:16:00 07.05.2026

8.5.96 25 kHz FM, UL Mask C, AGC+3, 804 MHz




08:16:32 07.05.2026

8.5.97 C4FM, UL Mask C, AGC, 804 MHz




15:34:45 05.05.2026

8.5.98 C4FM, UL Mask C, AGC+3, 804 MHz




08:51:12 07.05.2026

8.5.99 H-CPM, UL Mask C, AGC, 804 MHz




15:42:10 05.05.2026

8.5.100 H-CPM, UL Mask C, AGC+3, 804 MHz




15:43:35 05.05.2026

8.5.101H-DQPSK, UL Mask C, AGC, 804 MHz




15:45:38 05.05.2026

8.5.102 H-DQPSK, UL Mask C, AGC+3, 804 MHz




15:46:27 05.05.2026

8.5.103 6.25 kHz, FM, UL Mask H, AGC, 806 MHz




08:33:04 07.05.2026

8.5.104 6.25 kHz, FM, UL Mask H, AGC+3, 806 MHz




08:34:19 07.05.2026

8.5.105 12.5 kHz, FM, UL Mask H, AGC, 806 MHz




08:35:04 07.05.2026

8.5.106 12.5 kHz, FM, UL Mask H, AGC+3, 806 MHz




08:35:39 07.05.2026

8.5.107 25 kHz FM, UL Mask H, AGC, 806 MHz




08:36:24 07.05.2026

8.5.108 25 kHz FM, UL Mask H, AGC+3, 806 MHz




08:36:57 07.05.2026

8.5.109 C4FM, UL Mask H, AGC, 806 MHz




08:38:15 07.05.2026

8.5.110C4FM, UL Mask H, AGC+3, 806 MHz




08:39:55 07.05.2026

8.5.111 H-CPM, UL Mask H, AGC, 806 MHz




08:40:54 07.05.2026

8.5.112H-CPM, UL Mask H, AGC+3, 806 MHz




08:41:52 07.05.2026

8.5.113H-DQPSK, UL Mask H, AGC, 806 MHz




08:46:23 07.05.2026

8.5.114H-DQPSK, UL Mask H, AGC+3, 806 MHz




08:45:43 07.05.2026

8.5.1156.25 kHz, FM, UL Mask D, AGC, 816 MHz




13:41:43 08.05.2026

8.5.1166.25 kHz, FM, UL Mask D, AGC+3, 816 MHz




13:42:35 08.05.2026

8.5.11712.5 kHz, FM, UL Mask D, AGC, 816 MHz




14:10:13 08.05.2026

8.5.11812.5 kHz, FM, UL Mask D, AGC+3, 816 MHz




14:11:09 08.05.2026

8.5.11925 kHz FM, UL Mask D, AGC, 816 MHz




08:59:54 07.05.2026

8.5.120 25 kHz FM, UL Mask D, AGC+3, 816 MHz




09:04:34 07.05.2026

8.5.121C4FM, UL Mask D, AGC, 816 MHz




15:00:21 07.05.2026

8.5.122 C4FM, UL Mask D, AGC+3, 816 MHz



15:01:01 07.05.2026

8.5.123 H-CPM, UL Mask D, AGC, 816 MHz




15:02:15 07.05.2026

8.5.124 H-CPM, UL Mask D, AGC+3, 816 MHz




15:02:58 07.05.2026

8.5.125 H-DQPSK, UL Mask D, AGC, 816 MHz




14:57:28 07.05.2026

8.5.126 H-DQPSK, UL Mask D, AGC+3, 816 MHz




14:58:14 07.05.2026

8.5.127 6.25 kHz, FM, UL Mask D, AGC, 823 MHz




14:21:59 08.05.2026

8.5.128 6.25 kHz, FM, UL Mask D, AGC+3, 823 MHz




14:22:50 08.05.2026

8.5.129 12.5 kHz, FM, UL Mask D, AGC, 823 MHz




14:24:04 08.05.2026

8.5.130 12.5 kHz, FM, UL Mask D, AGC+3, 823 MHz




14:24:52 08.05.2026

8.5.13125 kHz FM, UL Mask D, AGC, 823 MHz



09:22:27 07.05.2026

8.5.132 25 kHz FM, UL Mask D, AGC+3, 823 MHz



09:23:06 07.05.2026

8.5.133 C4FM, UL Mask D, AGC, 823 MHz



14:44:37 07.05.2026