



360 Herndon PKWY
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

FCC ID:	P57-AU2006
Report NO:	2001345
Model NO:	Fiber Leap
Customer:	Telaxis Communications Corp.


Table of Contents -- Plots

Identifier	Description	Notes
<u><i>Plots for Access Unit A</i></u>		
Plot #1	Access Unit A, OC12 Modulation, Total Band 57-64GHz	
Plot #2	Access Unit A, OC12 Modulation, 26 dB Bandwidth	EBW=1879.7 MHz
Plot #3	Access Unit A, OC3 Modulation, Total Band 57-64GHz	
Plot #4	Access Unit A, OC3 Modulation, 26 dB Bandwidth	EBW=1873.6 MHz
<u><i>Plots for Access Unit B</i></u>		
Plot #5	Access Unit B, OC12 Modulation, Total Band 57-64GHz	
Plot #6	Access Unit B, OC12 Modulation, 26 dB Bandwidth	EBW=1884.2 MHz
Plot #7	Access Unit B, OC3 Modulation, Total Band 57-64GHz	
Plot #8	Access Unit B, OC3 Modulation, 26 dB Bandwidth	EBW=2020.6 MHz



360 Herndon PKWY
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


FCC ID:	P57-AU2006
Report NO:	2001345
Model NO:	Fiber Leap
Customer:	Telaxis Communications Corp.





360 Herndon PKWY
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


FCC ID:	P57-AU2006
Report NO:	2001345
Model NO:	Fiber Leap
Customer:	Telaxis Communications Corp.





360 Herndon PKWY
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


<i>FCC ID:</i>	P57-AU2006
<i>Report NO:</i>	2001345
<i>Model NO:</i>	Fiber Leap
<i>Customer:</i>	Telaxis Communications Corp.





360 Herndon PKWY
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


<i>FCC ID:</i>	P57-AU2006
<i>Report NO:</i>	2001345
<i>Model NO:</i>	Fiber Leap
<i>Customer:</i>	Telaxis Communications Corp.





360 Herndon PKWY
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


<i>FCC ID:</i>	P57-AU2006
<i>Report NO:</i>	2001345
<i>Model NO:</i>	Fiber Leap
<i>Customer:</i>	Telaxis Communications Corp.





360 Herndon PKWY
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


<i>FCC ID:</i>	P57-AU2006
<i>Report NO:</i>	2001345
<i>Model NO:</i>	Fiber Leap
<i>Customer:</i>	Telaxis Communications Corp.





360 Herndon PKWY
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


FCC ID:	P57-AU2006
Report NO:	2001345
Model NO:	Fiber Leap
Customer:	Telaxis Communications Corp.





360 Herndon PKWY
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

FCC ID:	P57-AU2006
Report NO:	2001345
Model NO:	Fiber Leap
Customer:	Telaxis Communications Corp.





360 Herndon PKWY
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

<i>FCC ID:</i>	P57-AU2006
<i>Report NO:</i>	2001345
<i>Model NO:</i>	Fiber Leap
<i>Customer:</i>	Telaxis Communications Corp.

This page left blank intentionally.