



Intertek Testing Services

ETL SEMKO

Report No.: 0212997
Mode: Talk

Tested By: Hong, Report No.: 0212997

Scan Settings (1 Range)

|----- Frequencies -----|----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge	Transducer No.	Start	Stop	Name
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB	21	9k	30M	EW0698


Final Measurement: x QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

dBuV



PAGE 1

Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 0212997
Mode: Talk

Tested By: Hong, Report No.: 0212997

Scan Settings (1 Range)

|----- Frequencies -----|----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement

no Results

Ctrl No.: N/A