

1.) Please review the text for making the peak power measurement on page 65 of Annex A. This procedure makes no sense and is not relevant to a peak power meter. Please revise test report.

2.) Please provide a list for the pseudo-random hopping sequence. This is necessary for all frequency hoppers. I suggest adding this to the Operational Description.

Thanks,

Bill

~~~~~  
~ William H. Graff, NARTE Certified  
~ President and Director of Engineering  
~ AmericanTCB, Inc.  
~ 6731 Whittier Ave.  
~ McLean, VA 22101  
~ <mailto:whgraff@americanTCB.com>  
~ mobile <mailto:whgraff@attglobal.net>  
~ Direct Phone: (480)317-0683  
~ Direct Mobile: (602)790-6788  
~ Corporate Phone: (703)847-4700  
~ Corporate FAX: (703)847-6888  
~  
~~~~~