


INTERTEK TESTING SERVICE

Report No.: 14031417HKG-001

Equipment Photographs

Model: WR780

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14031417HKG-001

Equipment Photographs

Model: WR780

(Internal)




INTERTEK TESTING SERVICE

Report No.: 14031417HKG-001

Equipment Photographs

Model: WR780

(Internal)




INTERTEK TESTING SERVICE

Report No.: 14031417HKG-001

Equipment Photographs

Model: WR780

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14031417HKG-001

Equipment Photographs

Model: WR780

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14031417HKG-001

Equipment Photographs

Model: WR780

(Internal)





INTERTEK TESTING SERVICE

Report No.: 14031417HKG-001

Equipment Photographs

Model: WR780

(Internal)



INTERTEK TESTING SERVICE

Report No.: 14031417HKG-001

Equipment Photographs

Model: WR780

(Internal)




INTERTEK TESTING SERVICE

Report No.: 14031417HKG-001

Equipment Photographs

Model: WR780

(Internal)



INTERTEK TESTING SERVICE

Report No.: 14031417HKG-001

Equipment Photographs

Model: WR780

(Internal)

