



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

15 Internal EUT Photographs



Top cover removed showing RF PCB




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



Bottom cover removed




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



Top RF PCB




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



Bottom RF PCB



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



Inside front handset





360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Outside back handset



Label on back of handset




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



Inside back handset




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



Top handset PCB




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>




Bottom handset PCB



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>




Handset showing PCB installed



Outside top plate



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>




Inside top cover




Outside bottom cover



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



Inside bottom cover



Label inside bottom cover