

Spritzer | TPN-Q146 | Y63 | INTEL

Font:

Print area - Gotham book 4pt

Etching area- Gotham book 4pt

Contains Intel radio 3160HMW
Contains FCC ID: PD93160H
IC: 1000M-3160H

RMN/TPN-Q146 INPUT/19.5V 2.31A CS10 Made in China www.hp.com
European Regulatory Address: HP,
HQ-TRE/71004 Boeblingen, Germany
CAN ICES-3(B)/NMB-3(B)



LISTED
I.T.E.
E142692
C010



WLAN module:
Wilkins (716282-001)



HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com

HP-TPN-Q146-001
AC: 19.5V 2.31A
www.hp.com