

Appendix C – SAR Test Setup Photos




Test Position Back 0 mm Gap

Note: AC power removed during testing



Test Position Top 0 mm Gap

Note: AC power removed during testing



Test Position Right 0 mm Gap

Note: AC power removed during testing



Front of Device Tablet Mode



Back of Device Tablet Mode



Laptop Mode