

Appendix C – SAR Test Setup Photos



Test Position Back 0 mm Gap

Note: All Cables are removed prior to testing.



Front of Device Laptop Mode