

Appendix C – SAR Test Setup Photos



Test Position Back 0 mm Gap

Note: All cables removed prior to testing.



Test Position Bottom 0 mm Gap

Note: All cables removed prior to testing.



Test Position Laptop 0 mm Gap



Front of Device Tablet Mode CF



Back of Device Tablet Mode CF



Front of Device Laptop Mode CF



Front of Device Tablet Mode AL



Back of Device Tablet Mode AL



Front of Device Laptop Mode AL