

Inside view of EUT




Top side view of main board



Bottom side view of main board




View of cable tuner #1, #2



Report no. ETLT171129.0141, Page D4 of D6

Inside view of cable tuner #1, #2



Report no. ETLT171129.0141, Page D5 of D6

View of cable tuner #3

