Andrew Perkins
American Microsystems, Ltd.
2190 Regal Parkway
Euless, TX 76040
Phone: (817) 571-9015
Fax: (817) 685-6232

Subject: Changes To PGAM6000

Dear Reviewer,

American Microsystems, Ltd. (AMS) needs to make changes to Form 731 and other attached files. At this point of the process, the beginning, the simplest approach to solving this problem would be to remove the project from your database, thereby allowing me to start over, together with our OET test lab National Technical Systems. However, if you cannot comply with this request, here are the necessary changes.

Alternative, make these changes:

FORM 731:

Item 6:

Firm Name: American Microsystems, Ltd.
Telephone: (817) 571-9015
Ext. 107
Fax No.: (817) 685-6232
First Name: Andrew
Middle Initial: L
Last Name: Perkins
Address Line 1: 2190 Regal Parkway
P.O. Box: "blank", delete word the Plano
City: Euless
State: TX
Email: aperkins@amltd.com

Item 7:

Firm Name: American Microsystems, Ltd.
Telephone: (817) 571-9015
Ext. 130
Fax No.: (817) 685-6232
First Name: Dave
Middle Initial: "blank"
Last Name: Bothel
Address Line 1: 2190 Regal Parkway
P.O. Box: "blank", delete word the Plano

City: Euless
State: TX
Email: dbothel@amltd.com

Item 8:

47 CFR 0.459: **YES**

Item 9:

47 CFR 0.457(d)(1)(ii): **NO**

Item 10:

Equipment code: use DXT (not DXX) – DXT is a Part 15 low power transceiver, RX verified

Description: M6000 RF Barcode Reader
FCC Rule Parts: 47 CFR 15.249

Item 12

Frequency range in MHz: 916.5
Rated RF power in watts: .00025 (0.25mW) remove the leading zero currently on form
Frequency tolerance: .022% (+-200kHz) The current answer is incorrect.

Item 13:

(a) a composite device: **NO**
(b) part of a system that operates with, or marketed with: **YES**
(c) the related application: has been filed at the same time as the FCC ID listed to the right: (PGAM6200)

This completes changes for Form 731:

Exhibits to remove:

1.) Remove the User's Manual

2.) Remove the Attestation Statement, for the document requesting Confidentiality – the proper form of document for this is the Cover Letter one that is currently there.

3.) Remove THIS letter, delete.doc. There is no reason to keep track of mistakes.

Contact me if there are any questions. Thank You Andrew Perkins