



HERMON LABORATORIES

September 11, 2006

American TCB
6731 Whittier Ave
Suite C110
McLean, VA 22101
Attn: Mr. Timothy Johnson, Examining Engineer

RE: your e-mail dated September 8, 2006; Airspan Networks Ltd.
FCC ID: PIDMMAX58, ATCB003941

Dear Mr. Johnson,
Please find below the answers to your questions.

- 1) The photograph 5A was added, the exhibit "Internal_photos_17233_rev1" was uploaded on September 11, 2006.
- 2) The photograph 19 was added, the exhibit "Internal_photos_17233_rev1" was uploaded on September 11, 2006.
- 3) The label was corrected, the file "Label_location_17233_rev1" was uploaded on September 11, 2006.
- 4) The corrected "User_Manual_17233_rev1" was uploaded on September 11, 2006.
- 5) The block diagram in the test report was corrected, file "AIRRAD_FCC.17233_rev1" was uploaded on September 11, 2006

Thank you for your assistance and support.

Sincerely,

Marina Cherniavsky,
certification engineer
Hermon Laboratories