

INTERTEK TESTING SERVICE

Report No.: 16030519HKG-003

Equipment Photographs

Model : DNH03R

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16030519HKG-003

Equipment Photographs

Model : DNH03R

(Internal)



FCC ID: PIYDNH03-16A5R
IC: 4390C-DNH0316A5R



INTERTEK TESTING SERVICE

Report No.: 16030519HKG-003

Equipment Photographs

Model : DNH03R

(Internal)



FCC ID: PIYDNH03-16A5R
IC: 4390C-DNH0316A5R


INTERTEK TESTING SERVICE

Report No.: 16030519HKG-003

Equipment Photographs

Model : DNH03R

(Internal)



FCC ID: PIYDNH03-16A5R

IC: 4390C-DNH0316A5R



INTERTEK TESTING SERVICE

Report No.: 16030519HKG-003

Equipment Photographs

Model : DNH03R

(Internal)



FCC ID: PIYDNH03-16A5R
IC: 4390C-DNH0316A5R


INTERTEK TESTING SERVICE

Report No.: 16030519HKG-003

Equipment Photographs

Model : DNH03R

(Internal)



FCC ID: PIYDNH03-16A5R

IC: 4390C-DNH0316A5R


INTERTEK TESTING SERVICE

Report No.: 16030519HKG-003

Equipment Photographs

Model : DNH03R

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16030519HKG-003

Equipment Photographs

Model : DNH03R

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16030519HKG-003

Equipment Photographs

Model : DNH03R

(Internal)

