


INTERTEK TESTING SERVICE

Report No.: 17041542HKG-003

Equipment Photographs

Model : FFY80

(Internal)



FCC ID: PIYFFY80-17A5R



INTERTEK TESTING SERVICE

Report No.: 17041542HKG-003

Equipment Photographs

Model : FFY80

(Internal)



FCC ID: PIYFFY80-17A5R


INTERTEK TESTING SERVICE

Report No.: 17041542HKG-003

Equipment Photographs

Model : FFY80

(Internal)



FCC ID: PIYFFY80-17A5R



INTERTEK TESTING SERVICE

Report No.: 17041542HKG-003

Equipment Photographs

Model : FFY80

(Internal)



FCC ID: PIYFFY80-17A5R


INTERTEK TESTING SERVICE

Report No.: 17041542HKG-003

Equipment Photographs

Model : FFY80

(Internal)



FCC ID: PIYFFY80-17A5R



INTERTEK TESTING SERVICE

Report No.: 17041542HKG-003

Equipment Photographs

Model : FFY80

(Internal)



FCC ID: PIYFFY80-17A5R