
July 9, 2004
Federal Communications Commission
Equipment Approval Services
7435 Oakland Mills Road
Columbia, MD 21046

SUBJECT : Hyundai ImageQuest Co., Ltd.
FCC ID: PJILT32AW000
FCC Part 15 Subpart B Certification


Gentlemen:

Transmitted herewith, on behalf of Hyundai ImageQuest Co., Ltd. is an application for a FCC Part 15 Subpart B Certification of the following 32-inch LCD Monitor:

FCC ID : PJILT32AW000
Model No. / Type No.: HQL320WR / LT32AW000

Attached is the applicant's Cover Letter, External/Internal Photos, Test Set-Up Photos, FCC ID & Label Location, User Manual, Block Diagram and Test Report.

Should you have any questions or comments concerning the above, please contact the undersigned.



KI SOO KIM
EMC MANAGER

cc: Mr. HEE JUNG KIM ----- R & D CENTER / MANAGER

•Solution for EMI

We, Hyundai ImageQuest CO., LTD. , announce that all modifications will be incorporated into each unit sold in the U.S.

- 1. Attach copper foil on the mainframe cover for OSD and audio signal cable fixed.
And Apply a ferrite core to the audio, video and OSD board signal cable.**
- 2. Attach a gasket on the LCD panel back cover inside.**
- 3. Attach a gasket on the main board case.**
- 4. Attach a gasket on the LCD panel case.**
- 5. Attach a gasket on the main board.**
- 6. Attach a gasket on tuner and tuner board.**

(Please refer to next page of the photographs for Solution for EMI)


Hyundai ImageQuest CO., LTD.

2004. 7. 9


**R & D CENTER / MANAGER
HEE JUNG KIM**




1. Attach copper foil on the mainframe cover for OSD and audio signal cable fixed.
And Apply a ferrite core to the audio, video and OSD board signal cable.



2. Attach a gasket on the LCD panel back cover inside.




3. Attach a gasket on the main board case.



4. Attach a gasket on the LCD panel case.



5. Attach a gasket on the main board .



6. Attach a gasket on tuner and tuner board.

