



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

March 13, 2003

RE: Linksys Group Inc.

FCC ID: PKW-BEFCMUH4

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) Since the TX PCMCIA card is also built by Linksys, please provide the block diagram of the Tx portion of the device. Please note that the block diagram should show the frequencies of all oscillators in the device (CFR 2.1033(a)(5)).
- 2) Please provide a photograph of the label of the PC card which shows its FCC ID Number. Note the label of the cable modem references FCC ID: FCC ID:PKW-WPC11-V3.
- 3) The operational description was uploaded as confidential, but not listed in the confidentiality letter. Please confirm if this exhibit is considered confidential and if so, please updated the confidentiality letter.
- 4) The parts list is not necessary. Please correct the confidentiality letter by removing this.
- 5) Please provide the schematics for the PCMCIA .
- 6) The label contains information relative to Part 68 (Ringer Equivalence, FCC Registration Number, and USOC codes). If this device does not contain a telco interface, this information is not necessary. If this information is not necessary, please remove.
- 7) The users manual does not appear to contain any information regarding use of the PCMCIA Card. Additionally, information required by 15.
- 8) The required statements given in 15.21 should be added to the users manual. Additionally, the users manual is missing information regarding RF exposure statements.
- 9) Please explain what precautions are built into the device so that it only functions with the particular PCMCIA card specified.
- 10) Given that the TX is a 2.4 GHz TX, please explain why there is not any radiated spurious emissions data for > 1 GHz.
- 11) Please provide information regarding the VBW and RBW of the plots provided at the bandedge.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.