

American Telecommunications Certification Body Inc.

6731 Whittier Ave, McLean, VA 22101

September 2, 2001

RE: The Linksys Group, Inc
FCC ID: PKW-WMP11

Please address the following concerns.

- 1.) Form 731 is rating the power output of the card in terms of EIRP. This is incorrect. Please resubmit a new Form 731 showing conducted power.
- 2.) The photographs cannot be held Confidential. Please resubmit new Request for Confidentiality letter.
- 3.) Pages 16, 17, and 18 indicate a common SMA connector is used with this device. This is not permitted. Please refer to 47CFR 15.203 for further guidance. As of this writing, "non-standard" connectors {i.e. reverse threaded SMA connectors} are permitted. There is no standard list of permissible connectors from which you select. This is a continuing hot topic at the FCC's OET. I suggest you contact Joe Dichoso if additional guidance is required.



William H. Graff
Examining Engineer
President and Director of Engineering
<mailto:whgraff@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.