



American Telecommunications Certification Body Inc.

6731 Whittier Ave, McLean, VA 22101

June 13, 2002

RE: FCC ID: PL6-MMDS-CPE-R2

Attention: Tom Tidwell and Denise Godfrey

I have a few comments on this Application.

- 1 Pages 20 to 31 of the test report are blank. Please provide the data on the blank pages.
- 2 Pages 36 to 55 of the test report are blank. Please provide the data on the blank pages.
- 3 There appears to be a ferrite on the power cord of the device. Is this a molded ferrite that comes with the power supply or is it added to make the device compliant. If it is added please provide a statement to the effect that it will be required on the power input line.

Dennis Ward

<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.