

Subject: RE: PL6-MMDS-CPE-R2 request for info
Date: Fri, 14 Jun 2002 09:19:11 -0500
From: Denise.Godfrey@nemkona.com
To: dennis@yosemite.net

Hi Dennis

I have just uploaded the test report for the above application to your site. I guess the data was in there but something went wrong when we converted to PDF.

regarding item 2) The ferrite is molded in and is a part of the power supply. It was not added during testing to make the CPE complaint.

Hope this clears up these issues. Let me know

Best Regards

Denise

-----Original Message-----

From: Dennis Ward [mailto:dennis@yosemite.net]
Sent: Thursday, June 13, 2002 2:16 AM
To: Tom Tidwell; Denise Godfrey
Subject: PL6-MMDS-CPE-R2 request for info

Hi Tom / Denise

jsut a couple things on this one and I can issue the grant. Some pages in the report are blank and a question about a ferrite on the power cord. Please see attached request.

Thanks

Dennis Ward
dward@americantcb.com