













R81 상판과 이중으로 잡혀 있음.



20040427. J3 20핀으로 변경




D:\MY DOCUMENTS\I MY RECEIVED FILES\HAN-500_MAIN_REV_ME-20040524.DSN

amac




HAN-500_MAIN

Title			
04.Flash Memory, Connector			
Size	Document Number	Edited By	Rev
A4		Jinny Kim	MD
Date:	Tuesday, June 29, 2004		Sheet 4 of 6



D:\MY DOCUMENTS\IMY RECEIVED FILES\HAN-500_MAIN_REV_ME-20040524.DSN

amac		HAN-500_MAIN	
Title		05.AUDIO Interface	
Size A4	Document Number	Edited By Jinny Kim	Rev MD
Date:	Tuesday, June 29, 2004	Sheet	5 of 6



D:\MY DOCUMENTS\IMY RECEIVED FILES\HAN-500_LCD_REV_ME-20040524.DSN

amac

HAN-500_LCD

Title			
03.SD, KEY, EL			
Size A4	Document Number	Edited By Jinny Kim	Rev MD
Date:	Tuesday, May 25, 2004	Sheet	3 of 3