

BRANFORD L I M I T E D


To: ITS
Attn: Miss Rita Chan
From: Dickson - BRANFORD LTD.
Date: 13 Jun 2001

RE: BB3265 Musde Truck/BB3267 Beetle-Bug

It is confirmed that the below label will be added on the back of the remove controller as below figure.

FCC ID : PN6RC27232653267

This device compiles with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.



15TH FLOOR, RAILWAY PLAZA, 39 CHATHAM ROAD SOUTH, TSIMSHATSUI, KOWLOON, HONG KONG.
TEL: (852) 2368-0613 FAX: (852) 2368-2087