

BRANFORD

L I M I T E D

To: ITS
Attn: Miss Rita Chan
From: Dickson - BRANFORD LTD.
Date: 23 May 2001

RE: BD80239SP SCOOTER

It is confirmed that the below label will be added on the back of the remove controller as below figure.

FCC ID: PN6RC276BD80239SP

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

42mm

22mm

