


DUT on OATS



DUT on OATS (close-up)





Peak Power Meas. Setup


# RF Setup Photo(1)



# RF Setup Photo (2)



# Setup Photo (3)



# Setup Photo (4)

