


INTERTEK TESTING SERVICE

Report No.: 17041140HKG-001 (FCC)
17041140HKG-002 (IC)

Equipment Photographs

Model : 14428

(Internal)



FCC ID: PQN1442813M56
IC: 4438B-14428



INTERTEK TESTING SERVICE

Report No.: 17041140HKG-001 (FCC)
17041140HKG-002 (IC)

Equipment Photographs

Model : 14428

(Internal)



FCC ID: PQN1442813M56
IC: 4438B-14428


INTERTEK TESTING SERVICE

Report No.: 17041140HKG-001 (FCC)
17041140HKG-002 (IC)

Equipment Photographs

Model : 14428

(Internal)



FCC ID: PQN1442813M56
IC: 4438B-14428


INTERTEK TESTING SERVICE

Report No.: 17041140HKG-001 (FCC)
17041140HKG-002 (IC)

Equipment Photographs

Model : 14428

(Internal)



FCC ID: PQN1442813M56
IC: 4438B-14428


INTERTEK TESTING SERVICE

Report No.: 17041140HKG-001 (FCC)
17041140HKG-002 (IC)

Equipment Photographs

Model : 14428

(Internal)



FCC ID: PQN1442813M56
IC: 4438B-14428



INTERTEK TESTING SERVICE

Report No.: 17041140HKG-001 (FCC)
17041140HKG-002 (IC)

Equipment Photographs

Model : 14428

(Internal)



FCC ID: PQN1442813M56
IC: 4438B-14428


INTERTEK TESTING SERVICE

Report No.: 17041140HKG-001 (FCC)
17041140HKG-002 (IC)

Equipment Photographs

Model : 14428

(Internal)



FCC ID: PQN1442813M56
IC: 4438B-14428

INTERTEK TESTING SERVICE

Report No.: 17041140HKG-001 (FCC)
17041140HKG-002 (IC)

Equipment Photographs

Model : 14428

(Internal)



FCC ID: PQN1442813M56
IC: 4438B-14428