

## INTERTEK TESTING SERVICE


---

Report: 14070167HKG-001

### Equipment Photographs

Model : (FCC) 72600 / (IC) 72600WM

(Internal)



## INTERTEK TESTING SERVICE



---

Report: 14070167HKG-001

### Equipment Photographs

Model : (FCC) 72600 / (IC) 72600WM

(Internal)



## INTERTEK TESTING SERVICE



---

Report: 14070167HKG-001

### Equipment Photographs

Model : (FCC) 72600 / (IC) 72600WM

(Internal)



---

FCC ID: PQN7260013M56WM  
IC: 4438B-72600WM



## INTERTEK TESTING SERVICE

Report: 14070167HKG-001

### Equipment Photographs

Model : (FCC) 72600 / (IC) 72600WM

(Internal)



FCC ID: PQN7260013M56WM  
IC: 4438B-72600WM

## INTERTEK TESTING SERVICE



---

Report: 14070167HKG-001

### Equipment Photographs

Model : (FCC) 72600 / (IC) 72600WM

(Internal)



## INTERTEK TESTING SERVICE



---

Report: 14070167HKG-001

### Equipment Photographs

Model : (FCC) 72600 / (IC) 72600WM

(Internal)



---

FCC ID: PQN7260013M56WM  
IC: 4438B-72600WM

## INTERTEK TESTING SERVICE



---

Report: 14070167HKG-001

### Equipment Photographs

Model : (FCC) 72600 / (IC) 72600WM

(Internal)



## INTERTEK TESTING SERVICE

---

Report: 14070167HKG-001

### Equipment Photographs

Model : (FCC) 72600 / (IC) 72600WM

(Internal)

