

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124


Worst Case Position

(Above 1GHz:Horizontal: X-3-axis / Vertical:X-1-axis)
(Below 1GHz:Horizontal: Y-2-axis / Vertical:Y-2-axis)


X-1-axis




Y-1-axis




X-2-axis




Y-2-axis



X-3-axis




Y-3-axis




Worst Case Position


Z-1-axis



Z-2-axis



Z-3-axis



End of Report