



Report No.: 0103504
Talk Mode

Tested by:

[illegible]

```
----- Receiver Settings -----
```

Start	100%	100%	100%	Detector	1-1	Time	Atten	Preamp	OpRge
450k	100%	100%	100%	5k	20ns	AUTO	LN	OFF	60dB

Final Release Date: 07/20/2016

Transducer No	Start	Stop	Name
21	9k	30M	EW0698



Intertek Testing Services

ETL SEMKO

Report No.: 0103504
Talk Mode

Tested By: Honq, Report No.:0103504

Scan Settings (1 Range)

|----- Frequencies -----| |----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement

no Results