



WILSON CONNECTIVITY
1444 E Venture Dr, St. George, UT 84790
T. 1-800-204-4104 F. 1-435-673-0899 E. info@weboost.com
www.wilsonconnectivity.com

Feb 11, 2026

Attestation For Signal Booster: FCC ID PWO086

Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046
USA

RE: Attestation for FCC ID: PWO086

To Whom It May Concern:

Each Signal Booster certificated under FCC ID PWO086 is manufactured and individually tested to ensure FCC compliance:

- 1) Licensee consent is not required for FCC certification equipment authorization purposes, but licensee consent does remain applicable per 20.21 provisions for both provider specific and wideband boosters.
- 2) NPS and other compliance/safeguard features have been implemented.
- 3) NPS and other compliance/safeguard features are defaulted to be "On" (in operation).
- 4) NPS and other compliance/safeguard features cannot be field reconfigured, disabled, or removed.
- 5) This consumer booster is not user programmable, does not need fine tuning or adjustment, and does not require professional installation.
- 6) Future software upgrade will not cause non-compliance.

Sincerely,

A handwritten signature in black ink, appearing to read "Derrick Stout", written in a cursive style.

Derrick Stout



WILSON CONNECTIVITY
1444 E Venture Dr, St. George, UT 84790
T. 1-800-204-4104 F. 1-435-673-0899 E. info@weboost.com
www.wilsonconnectivity.com

Engineering Manager