



WILSON CONNECTIVITY
1444 E Venture Dr, St. George, UT 84790
T. 1-800-204-4104 F. 1-435-673-0899 E. info@weboost.com
www.wilsonconnectivity.com

Feb 3, 2026

To: Whom It May Concern

Alternative Warning Label Placement

This letter is to request alternative warning label placement for the signal booster model number 470086. The signal booster is too small to fit the warning label as can be seen from the Label Placement and External Photos Exhibits. Instead, the warning can be found on page 8 of the User Manual.

Sincerely,

A handwritten signature in black ink, appearing to read "Derrick Stout", written in a cursive style.

Derrick Stout
Engineering Manager