



3301 E. Deseret Drive, St. George, UT 84790
www.wilsonelectronics.com • info@wilsonelectronics.com
phone 1-800-204-4104 • fax 1-435-656-2432

September 30, 2014

To: Whom it May Concern

Subject: Alternative Warning Label Placement

This letter is to request alternative warning label placement for the signal booster model number 460007. The signal booster is too small to fit the warning label. Instead, the warning can be found in the User Manual.

Sincerely,

A handwritten signature in black ink, appearing to read 'P. L. Cook', is written above the printed name.

Patrick L. Cook
Senior Research and Development Engineer