



3301 E. Deseret Drive, St. George, UT 84790
www.wilsonelectronics.com • info@wilsonelectronics.com
phone 1-800-204-4104 • fax 1-435-656-2432

June 24, 2014

To: Whom it May Concern

Subject: Alternative Warning Label Placement for FCC ID: PWO460009

The subject signal booster is too small to fit the warning label as can be seen from the Label Placement and External Photos exhibits. Instead, the warning can be found in the User Manual.

Sincerely,

A handwritten signature in black ink, appearing to read 'P. L. Cook', is written above the printed name.

Patrick L. Cook
Chief Technology Officer